BUILDING PERMIT STATUS



Permit Number: Job Address:

Job Name: EHRLICH/GENERATOR

Permit Status: Plan Review

Permit Issued Date:

Submitted Into Plan Review Date: 10/25/2021 11:50:22 AM

Application Date: 10/25/2021 11:49:23 AM

7111 SW 9 ST, PEMBROKE PINES, FL 33023

Required Plan Reviews

The reason for this section: The disciplines listed below are required to review and signoff on your plans in order for you to obtain a valid permit.

| Discipline | Status | Date |
|-------------|----------|------------------------|
| BUILDING | APPROVED | 2/7/2022 2:54:03 PM |
| ELECTRICAL | APPROVED | 2/6/2022 4:54:02 PM |
| ENGINEERING | APPROVED | 12/2/2021 9:15:34 AM |
| FIRE | N/A | 11/15/2021 12:21:42 PM |
| PLUMBING | DENIED | 3/30/2022 4:26:15 PM |
| ZONING | APPROVED | 2/2/2022 9:35:11 AM |

Permit Requirements

The reason for this section: Listed below are the individual requirements needed in order to obtain a permit, request inspectons and successfully close out the job here in the city.

| Requirement | Required At | Recieved |
|-------------------------------|--------------------------|----------|
| SBDD FINAL RELEASE | C/O Requirement | NO |
| PERMIT READY TO ISSUE/PICK UP | Permit Issue Requirement | NO |
| SBDD REVIEW | Permit Issue Requirement | NO |
| HOA AFFIDAVIT | Permit Issue Requirement | YES |
| NOC | Permit Issue Requirement | YES |
| FLOOD ZONE INFORMATION | Permit Issue Requirement | NO |